


*Spacing of Framing and TieRod Location to Match Existing Window Mullions. To Be Field Verified Prior to Fabrication.



| | | | | | | |
|--------------------|----------------------|------------------|--------------|--------------|-------------|---|
| Job Title | UANT Cancer Center | Customer | Skiles Group | Art | C. Peterson | APPROVAL _____ Client Approval Date _____ |
| Location | 801 W. Interstate 20 | Drawing # | 3849A | Date | 04/20/2009 | |
| City, State | Arlington, TX 76017 | Sales | Todd Price | Scale | As Shown | |

This drawing is the property of SIGN & AWNING SERVICES of FORT WORTH, TEXAS and all rights to its reproduction and display are reserved by SIGN & AWNING SERVICES.

Wall Connection Detail



4711 Vermont Ave • Fort Worth • Texas • 76110
Ph. (817)-926-7270

| | | | | | |
|--------------------|----------------------|------------------|--------------|--------------|-------------|
| Job Title | UANT Cancer Center | Customer | Skiles Group | Art | C. Peterson |
| Location | 801 W. Interstate 20 | Drawing # | 3849-WC1 | Date | 04/20/2009 |
| City, State | Arlington, TX 76017 | Sales | Todd Price | Scale | As Shown |

| |
|--------------------------|
| APPROVAL |
| _____ Client Approval |
| Date _____ |

This drawing is the property of SIGN & AWNING SERVICES of FORT WORTH, TEXAS and all rights to its reproduction and display are reserved by SIGN & AWNING SERVICES.

